

Sydney Harbour & Port Botany Harbour Master Instruction Register

HMI No.	Title	Issue date
HMI 034-2018	Port Botany - Ultra Large Container Ship Windage Area	04/10/2018
HMI 011-2021	Port Botany - Brotherson Dock 6 Crane Position: Special Conditions	13/04/2021
HMI 001-2023	Port Botany - Boom-Out Crane Requirements	10/02/2023
HMI 005-2024	Alteration of Berth Box – Southern Quay – Brotherson Dock	11/11/2024
HMI 001-2025	Safe Marine Pilot Transfer (MPT) Arrangement – Pilot Ladder	11/07/2025
HMI 002-2025	Sydney Harbour - Dynamic Under Keel Clearance (DUKC) Requirement for Tankers Berthing at Gore Cove	22/07/2025
HMI 003-2025	Port Botany – Change of VHF Working Channels from 68/69 to 87/88	29/07/2025
HMI 005-2025	Port Botany – Supplement to Harbour Master’s Direction, Section 5.2: Berth Requirements – Brotherson Dock 12	22/10/2025
HMI 006-2025	Port Botany – Vessel Exchange Protocol at BLB (For vessels less than 130 meters LOA)	31/10/2025
HMI 008-2025 (Internal Only)	Sydney Harbour and Port Botany - FSYC (Sycamore) Arrival/Departure/Transit Within VTS Coverage Area	19/12/2025
HMI 001-2026	Port Botany - BD6 Requirements During Quay Crane 14 Maintenance and Repair Works	09/02/2026